



Combi USA, Inc.

3520 Westinghouse Blvd., Suite B

Charlotte, NC 28273

PRSRT FIRST CLASS

U.S. POSTAGE

PAID

Lehigh Valley, PA

Permit No. 129

Safety Recall Notice

IMPORTANT SAFETY RECALL INFORMATION



U.S. Department of
Transportation

Issued in Accordance
With Federal Law



IMPORTANT SAFETY RECALL

This notice applies to your Coccoro Child Restraint, 8220.

Combi®

3520 Westinghouse Blvd., Suite B
Charlotte, NC 28273
CombiUSA.com

July 2016

Subject: Combi Coccoro Child Restraint Recall No.: 16C006 (Combi Recall No. 610)
Model Number: 8220
Manufacture Dates: January 2009 – June 2016

Dear Combi USA Consumer,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Combi USA, Inc., is recalling certain Coccoro Child Restraints, model number 8220, manufactured between January 2009 and June 2016. These seats fail to conform to the requirements of Federal Motor Vehicle Safety Standard No. 213, "Child Restraint Systems."

Product: Combi Coccoro Child Restraint



Recall Product Identification:

Brand	Model	Model Number	Description
Combi	Coccoro	8220104	Hazelnut
Combi	Coccoro	8220105	Licorice
Combi	Coccoro	8220102	Carrot Cake
Combi	Coccoro	822062	Keylime
Combi	Coccoro	822099	Cool Mint
Combi	Coccoro	8220103	Strawberry Shake
Combi	Coccoro	8220100	Cherry Pie
Combi	Coccoro	8220101	Chestnut
Combi	Coccoro	8220105A	Licorice
Combi	Coccoro	8220102A	Carrot Cake
Combi	Coccoro	822062A	Key Lime
Combi	Coccoro	8220100A	Cherry Pie
Combi	Coccoro	8220101A	Chestnut
Combi	Coccoro	8220134	Grape



3520 Westinghouse Blvd., Suite B
Charlotte, NC 28273
CombiUSA.com

The Issue:

Combi USA, Inc. (Combi) is recalling certain Coccoro Convertible Child Restraints, model number 8220, manufactured from January 1, 2009, to June 29, 2016. When the Coccoro car seat is installed in a forward-facing position and only secured with the vehicle's lap belt, excessive force may be transmitted to the car seat occupant in the event of a crash, increasing their risk of injury. As such, these child seats fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 213, "Child Restraint Systems."

This recall does not affect the use of the Coccoro car seat when installed in a rearward-facing position.

Remedy:

Combi will provide you with a cover to add to the bottom of the seat, free of charge. Parts are expected to be shipped around August 15, 2016.

Owners may obtain a remedy kit by calling Combi USA's Remedy Kit hotline at 1-888-232-3294 or by going to <http://registration.combiusa.com/recall>.

Combi USA, Inc. recommends always using the vehicle tether anchor, and the use of lower anchor (LATCH) belts or the vehicle lap-shoulder (3-point) belts with lock-off when installing your seat in a forward-facing position. Again, this recall does not affect the use of the Coccoro when installed rear facing.

Note:

After contacting your dealer and the Combi customer service, if you are still not able to have the noncompliance remedied without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, DC 20590 or call 1-888-327-4236 (TTY 1-800-424-9153); or go to <http://www.safercar.gov>.